



Dear Sir,

Our chain of custody number is TT-CC-004296.

FSC mix is 79.3% and FSC/NAUF will be on the order (invoice) accordingly.

Non-FSC/NAUF will be put on a separate order.

We buy special core and veneer to achieve it. Cut stock (Non FSC virgin wood) and PVA glue (to adhere the veneer to core with no NAUF) make up the remaining 20.7%.

Contributing LEED credits: IE.Q low emitting materials (composite wood), MR 7 Certified wood.

The particleboard core is approximately 79% of the door. The calculation for the recycled content is as follows

Recycled content = 20% (post - consumer + one half post-industrial)

We do not know the post-consumer so we assume it is 0%

The post-industrial is 79%, 1/2 of 79% is 39-1/2%

Thus recycled content needs to be 20%, but is 0% (post - consumer) + 39.5% = 39.5%

MR 4.1 requirement is 10%

MR 4.2 requirement is 20%

MR 5.2 is as follows:

Our doors are manufactured at our Riverview plant, located at 1575 Riverview Ave. , San Bernardino Ca. 92408.

The stiles and rails are manufactured at our Stockton plant, located in Stockton Ca. The core is manufactured at

Humboldt Flake board panels, 4700 West End Road, Arcata, Ca.95521, or Timber Products Company, 25 East Andrews Road in Medford Oregon, 97501

Our PVA glue contains no NAUF. We contribute to IE.Q 4.1 low emitting material (adhesives and sealants)

Signed,

Barry Reynolds
Haley Brothers